

Jesse Wolf House
210 E. Main Cross Street
Findlay
Hancock County
Ohio

HABS No. OH-2300

HABS
OHIO.
32-FIND,
1-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

4455
OH-2300
30-1-112
17

ARCHITECTURAL DATA FORM

| | | |
|---|-------------------|--|
| STATE Ohio | COUNTY Hancock | TOWN OR VICINITY City of Findlay |
| HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Jesse Wolf House (original owner of house) | | HABS NO. OH- 2300 |
| SECONDARY OR COMMON NAMES OF STRUCTURE None | | |
| COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 210 E. Main Cross Street, Findlay, Ohio 45840; UTM: 17.277670.4546220 | | |
| DATE OF CONSTRUCTION (INCLUDE SOURCE) Circa 1865 (Maps at Hancock County Historical Museum) | | ARCHITECT(S) (INCLUDE SOURCE) Not Known |
| SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The original single-family residence, which has been used as a duplex since 1939, has been determined by the Ohio Historic Preservation Office to be eligible for the National Register because the exterior represents a good, largely intact example of Italianate Architecture. | | |
| STYLE (IF APPROPRIATE) Italianate | | |
| MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Originally brick, with wood joists and floors on stone footings. Basement and garage floors are concrete. Wood windows and doors are located in wood and/or masonry frames. The hip roof is metal standing seam. | | |
| SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Irregularly shaped, the house is 58 feet deep, including the garage, and 30 feet wide. A five foot wide porch extends along two sides at the southeast corner. There is a 4 foot by 8 foot 8 inch alcove on the west side and a 7-1/2' jog on the northeast corner. | | |
| EXTERIOR FEATURES OF NOTE Wood Corbels; low pitch hip roof; porch on northwest corner; tall windows with arched frames. | | |
| INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The home has been modified into an up and down duplex. Each floor has a living room with brick fireplace, kitchen, dining area, two bedrooms and a bath. Living areas are separated by wide arched openings. The dining room on the main floor and the living rooms on both floors feature alcoves. | | |
| MAJOR ALTERATIONS AND ADDITIONS WITH DATES In the mid-1930's a garage was added. In 1938-39 the home was converted to a duplex. This renovation involved moving some interior walls, moving a bathroom, installing hardwood floors, redoing the kitchens, removing marble fireplaces and replacing them with brick fireplaces, adding a basement and reworking the porch. | | |
| PRESENT CONDITION AND USE Vacant and dilapidated | | |
| OTHER INFORMATION AS APPROPRIATE | | |
| SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Hancock County Historical Museum; Hancock County Recorder; Hancock County Auditor; Warren High, Woolpert Consultants; J.R. Brondes, Owner/Occupant 1919-87 | | |
| COMPILER, AFFILIATION James K. Dittus, Community Planner Hancock Regional Planning Commission | | DATE November 9, 1987 |

